



Wireless Coverage Survey

Heathrow Airport Terminals May 2016


Summary of Survey

- Completed using Airmagnet Survey Pro version 8.6 and 8.7
- Overall coverage is good and resilient
 - Improved in all public areas since last survey
- Rogue Access Points(APs) counts are low
 - Unauthorised APs found linked to increase in the number of printers


Terminal 2 Coverage Survey




T2A Departures Level 3 Coverage




T2A Gate Seating Level 2 Coverage




T2A Arrivals Level 1 Coverage




T2A Apron Level 0 Coverage



T2B Arrivals Level 2 Coverage



T2B Departures Level 1 Coverage



T2B Apron Level 0 Coverage




T2B Transfers Level -1 Coverage




Terminal 3 Coverage Survey



T3 Departures Level 2 Coverage




T3 Arrivals Level 1 Coverage



T3 Apron Level 0 Coverage



T3 Pier 7 Level 1 Coverage



Terminal 4 Coverage Survey




T4 Departures Level 2 Coverage



T4 Arrivals Level 1 Coverage




T4 Baggage Reclaim Level 1 Coverage




Terminal 5 Coverage Survey



T5A Departures Level 3 Coverage




T5 Gate Seating Level 2 Coverage




T5A Arrivals Level 1 Coverage



T5A Apron Level 0 Coverage




T5A Basement Level -1 Coverage




Terminal 5B Coverage Survey




T5B Lounge Level 3 Coverage




T5B Departures Level 2 Coverage




T5B Arrivals Level 1 Coverage




T5B Apron Level 0 Coverage



T5B Basement Level B2 Coverage



T5B Basement Level B4 Coverage




Terminal 5C Coverage Survey



T5C Departures Level 2 Coverage



T5C Arrivals Level 1 Coverage



T5C Apron Level 0 Coverage

